

SATISH M. GHANEKAR

LICENCED STRUCTURAL ENGINEER

4, Sant Kripa Commercial Complex, Yamunanagar, Nigdi, Pune - 44 Ph.: 7709009631, Mob.: 9370299631

E-mail: satishghanekar631@gmail.com, satishmghanekar@yahoo.co.in

Date: - 22-08-2023

TO WHOM SOEVER IT MAY CONCERN

STRUCTURAL STABILITY & COMPLETION CERTIFICATE

I have undertaken assignment as Structural Engineer for the Structural Work of the development work Of Completed School Building (G+1) & Including Compound Wall on Vishwakalyan English Medium School, Gat No-1207, Sonawane Wasti Road, P.C.M.C., Chikhali, Pune.

Sanctioned under No- BP / CHIKHALI / 05 / 2016 Dated :- 12-01-2016

The following listed firms/persons are associated with the work.

Architect	Mr. Umesh Namde
Owner	Vishwakalyan English Medium School (Mr. Jitendra R. Mehta)

Based on the reports, Photos and periodic Site inspection carried out by me/Through my engineer, from time to time, I certify that to the best of my knowledge the structural work is carried out as per the structural design & drawings prepared by me, and the memos & reports issued by me.

Based on the quality assurance certificate by the Licensed Supervising Engineer or the Builder/Contractor so qualified, I further certify that to the best of my knowledge, the structural work is carried out as per prescribed applicable standards and codes, rules, regulations and stipulations, the material used, workmanship and methodology employed for construction work are of accepted standards and the work is complete to render it fit for occupancy/for intended use. The Design is for EARTH QUAKE RESISTANCE ZONE III. This certificate is issued on the clear understanding that my overall design responsibility for the safety and proper performance of structural design ceases the moment any addition and or alteration or damage to the structural members/frame is caused by accident or by tampering with geometrical sections of structural members for any purpose, whatsoever or due to overloading of the structural, lack of maintaince or any act that is detrimental to the structure as a whole.

*This Certificate is issued only for Structural Stability of the Building & Compound Wall.

